DAVIS & FLOYD

SINCE 1954

Drainage Master Plan City of Isle of Palms

Council Workshop - May 9th 2023

WWW.DAVISFLOYD.COM

CONTENT

- Phase 4 Stormwater Masterplan
- Capital Improvement Plan
- Maintenance Program Review and Recommendations
- Development Regulations Review and Recommendations



Draft Report of the Phase 4 Stormwater Masterplan



"Drainage Study and Recommendations for Improvements" for City of Isle of Palms


January 2023

D|F Job No.: 031974.00

PREPARED FOR: City of Isle of Palms 1207 Palm Boulevard Isle of Palms, SC 29541

PREPARED BY: Aaron A. Akin, PhD and Ryne C. Phillips, PE Davis & Floyd, Inc. 1940 Algonquin Rd, Suite 301 Charleston, SC 29405 (843) 554-8602

Phase 4 Study Area



Phase 4 Survey & Monitoring




Example of a monitoring system placed on the island to monitor the rainfall and tidal conditions. This monitor was placed at the marina along the intracoastal waterway.




Example of surveying the drainage system inventory using the GPS units. This photo was taken at an outfall going to the intracoastal waterway.

Phase 4 Survey & Monitoring



An example of the results found from the monitoring systems placed around the island.


Phase 4 Existing and Proposed Conditions



The existing conditions were determined based on the field inventory taken from the survey. The results of a 10-year 24-hour SCS type III (6.60 in) Rainfall with typical tides is shown above for a section of the island on Ocean Blvd and Merrit Blvd.

The proposed conditions were determined to improve flooding conditions from the existing system. The results of a 10-year 24-hour SCS type III (6.60 in) Rainfall with typical tides is shown above for a section of the island on Ocean Blvd and Merrit Blvd.

Phase 4 Recommended Improvements




Tide gates are recommended to help alleviate frequent tidal flooding in the system.



Infiltration chambers are one of the many improvements proposed to the system.

Rank	Project	Estimated Cost
1	Charleston Boulevard	\$4,600,000
2	Ocean Boulevard	\$3,100,000
3	Outfall Improvements	\$11,900,000
4	Merritt Boulevard	\$1,000,000
5	Palm Boulevard	\$5,000,000
6	9 th Avenue Minor Improvements	\$1,200,000
7	Minor Drainage Improvements	\$19,500,000
	Total Estimated Project Costs	\$46,300,000


Charleston Boulevard Project



Existing Conditions

Proposed Conditions


Ocean Boulevard Project



Existing Conditions

Proposed Conditions

South Carolina Beach Advocates Conference (1/31/23)



Capital Improvement Plan

Phase 3 Assimilation (Projects recommended by T&H)



The existing conditions were determined based information provided by the town. The results of a 10-year 24-hour SCS type III (6.60 in) Rainfall is shown above for the Phase 3.

WWW.DAVISFLOYD.COM

Maintenance Review and Recommendations

- Maintenance Schedule
- Maintenance Tracking
- Adopt-a-Drain Program
- Online Reporting System

Following Following				
Monthly	Quarterly	Significant	King	Review/Recommendations
		Storms	Tides	
	x	x		Visually assess ditches for maintenance requirements and remove heavy debris, obstructions, sediment build up, or other maintenance as necessary (i.e., repair of ditch lining).
	x	x	x	Visually assess outfalls for maintenance needs and remove debris, obstructions, or provide other maintenance as necessary.
	x			Visually inspect, 'or vegetation growth and remove, as necessar
	x	x	x	Visur / insperrap and maintain (i.e., stone , senet) as ssary to support filter fabric / , sr. synett function ality.
	x	x		Vir ially inspect inlet sy as for sand / debris act aulation and mainte with truck vac cleanup or other statumethod as neclassary.
x		×	x	'sually inspect inlet grates for obstructions / debris and nup as necessary.
	x			Visually assess areas for signs of frequent flooding which could be due to blocked pipes or other drainage features. Consider investigating areas of concern with video inspections or other suitable method to identify potential repair needs.
				Visually assess areas for signs of frequent flooding which could be due to blocked pipes or other drainage features. Consider investigating areas of concern with video inspections or other suitable method to identify potential repair needs.
x				Visually assess public and private properties for evidence of unauthorized land disturbance activities (fill removal/placement, new construction, removal of buffers, other) Address observations as necessary.
x		x		Visually assess community debris removal practices for potential impacts to drainage system performance (i.e., obstructing drain access / increasing debris). Address observations as necessary.
	x			Visually inspect public area slopes and embankments for bare spots and replant areas, as necessary.

Development Regulations Review and Recommendations

- Revisions and Additions
- Best Management Practice Incentives

Title	Chapter	Article	Section(s)	Existing Ordinance	Stormwater Management Recommendation
Title 5 - Planning & Development	Chapter 4 - Zoning	Article 1 - General Provisions	Sec. 5-4-12 - Additional Regulations	p) Adding fill or importation of materials of any type, or re-contouring of a lot's existing contours, that increases a lot's existing ground elevation more than one (1) foot above existing road and results or may result in elevating an existing or proposed structure is strictly prohibited.	p) Adding fill or importation of materials of any type, or re-contouring of a lot's existin contours, that increases a lot's existing ground elevation more than one (1) foot above existing road and results or may result in elevating an existing or proposed structure is strictly prohibited, unless the elevated surface does not exceed 7.4 ft of elevation.
Title 5 - Planning & Development	Chapter 4 - Zoning	Article 1 - General Provisions	Sec. 5-4-12 - Additional Regulations	q) Any decrease in a lot's eximited and elevation is strictly prohimited.	OMIT Ordinance
Title 6 - Health and Sanitation	Chapter 1 - General Provisions	Article C - Maintenance of Property	Sec. 6-1-32 - Duty to keep property clean	c) It shall be unip to see or pusi litter from broding property, sidewalks and strin to streets, idewalks and the shard, hage sys is Sidewalk and strip sweepi, hur be picked up and put into house, in commercial material container.	er expanding reference to storm unage system to include explicitly natu and man-made drainage courses (i.e. ditches).
Title 5 - Planning & Development	Chapter 5 - Land Development Regulation	(-)	NEW ORDINANCE: Engineer Review of Development	Mine	A third-party engineer can be hired by the city to review development plans to determine if they are in compliance with land development regulations and other applicable Ordinances.
Title 5 - Planning & Development	Chapter 5 - Land Development Regulation	(-)	NEW ORDINANCE: Balance of Natural Sinks	None	For properties that fall within a select parameter*, any fill of sinks on the prope must be accompanied with an equal volumetric storage for stormwater that would be retained by that sink. This may it alleviated using BMPs or other forms of stormwater storage. Areas exempt from to required retention include: a) Stormwater runoff on the property floo directly into a creek or the Intercoastal Waterway. b) Stormwater runoff on the property floo directly into a stormwater ditch. The following BMPs can be considered as potential storage: a) Cisterns b) Rain Gardens c) Rain Barrels d) Retention Ponds